Name of Work:	Providing and asphalting to pot holes filling and Road cutting in Dasarahalli ward No.14
Work Order:	EE/DD/WO/356/2014-15, D:30 -03-2015.
Agency:	B.J.Kumara
B.R. No & Dated:	211/31-8-2015
Bill Amount:	Rs.946707.00
Job Code:	014-15-000017.
P. Code:	1771
Inspection Date:	

The Inspection work is done by me along with Concerned Engineers and ascertained that the said work is executed as per the requirements of site conditions and as shown in the photo's and premises the physical status of premises the work is pot.

ಮುಖ್ಯ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು.